

### Full Chain Status

S.Burdin




### Worked Fine (5M Events Passed)




### Voltage Measurements

- Russell's setup
- But
  - The original capacitor on AC
  - Measurements are on the hybrid


### Picture From Russell



# VDD Measurement on the Hybrid




## AVDD & DVDD Are Shortened on Hybrid Also



Full Chain stopped to work (no download). Work resumed only after removing the additional cable from the clock lines

## Additional 10µF on Hybrid



#### Conclusion

- VDD behavior in SiDet is close to the one in KSU
- 10µF on Hybrid added some small tail in VDD
- Additional study is needed on the clock bypass